National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 07/25/2002

DEN02LA026

Airplane

File No. 12062		02/18/2002	Englewood, CO	Aircraft Reg No. N6444C		Time (Local): 11:48 MST	
Engine Airc Numbe Operating (Type of Fligl	Make/Model: raft Damage: er of Engines: Certificate(s): ht Operation:	1 None		Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 1
Last Depart. Point: Destination: Airport Proximity: Airport Name: Centennial Runway Identification: 35L Runway Length/Width (Ft): Runway Surface: Runway Surface: On Airport Centennial 35L 7004 / 77 Asphalt Runway Surface Condition: Dry		Condition of Light: Day Weather Info Src: Weather Observation Facility Basic Weather: Visual Conditions Lowest Ceiling: 22000 Ft. AGL, Broken Visibility: 10.00 SM Wind Dir/Speed: 360 / 004 Kts Temperature (°C): 9 Precip/Obscuration: None / None					
Pilot-in-Command	Age:	53			Flight Ti	me (Hours)	
Certificate(s)/Rating(s) Private; Single-engine Land nstrument Ratings			Total All Aircraft: 1102 Last 90 Days: 60 Total Make/Model: 852				

The pilot said the landing approach was "a little fast, a little high," so he retarded the throttle and flared "too high." The airplane struck the runway "hard" with its nose landing gear, bounced, and touched down again. The nose landing gear collapsed and the airplane skidded to a halt off the left side of the runway.

Total Instrument Time: 161

Brief of Accident (Continued)

DEN02LA026

File No. 12062 02/18/2002 Englewood, CO Aircraft Reg No. N6444C Time (Local): 11:48 MST

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) FLARE - PREMATURE - PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows. The pilot flaring the airplane prematurely, which resulted in a hard landing.